



See Pages 35 & 36
for Lead Exits

GENERAL DIMENSIONS

Part #	Size	A	B	C	D	E	F	G	H			J	Ga
									STD	DEEP	X-DEEP		
C-100	1	2-1/2	3	2-1/16	1-11/16	2-1/8	2-5/8	2-5/32	21/32	7/8	1-5/32	7/32	22
C-200	1-1/8	2-13/16	3-3/8	2-3/8	1-13/16	2-7/16	3	2-15/32	27/32	1-3/32	-	7/32	22
C-300	1-1/4	3-1/8	3-3/4	2-5/8	2	2-11/16	3-5/16	2-25/32	7/8	1-1/8	-	7/32	22
C-400	1-3/8	3-7/16	4-1/8	3	2-5/16	3	3-11/16	3-1/16	15/16	1-3/16	1-1/2	7/32	22
C-500	1-1/2	3-3/4	4-1/2	3-5/16	2-17/32	3-5/16	4-1/16	3-13/32	1-1/16	1-3/16	1-1/2	7/32	22
C-700	1-3/4	4-3/8	5-1/4	3-7/8	2-15/16	3-7/8	4-3/4	-	1-1/4	1-5/8	-	9/32	20

Tolerances:
Decimal ± 0.005"
Fractional ± 1/64"

Phone:(513)793-8100
FAX:(513)793-0624

Links E-Mail: info@bahrsdie.com
Web: www.bahrsdie.com



Bahrs
Die & Stamping Co., Inc.
4375 Rossplain Rd., Cincinnati, OH 45236